

Project: Alaska Copper Works			Inspection Date: 6/19/19		
Project No.: 19ACW1		Technician: David DuBois			
System Performance:					
Was system running during the	inspection? Yes	⊠ No			
Flow Rates (gpm)	Influent n/a	Effluent n/a	The flows should be ~155 gpm		
Bag Filter #1 Pressures (psi)	Influent 8	Effluent 8	The bag filters should be replaced if differential pressure > 8 psi		
Bag Filter #2 Pressures (psi)	Influent 8	Effluent 6	-		
Carbon Filter Pressures (Lead)	Influentn/a	Effluent n/a	The carbon filters should be backflushed if differential		
Carbon Filter Pressures (Lag)	Influent <u>n/a</u>	Effluentn/a	pressure > 8 psi		
Were the bag filters replaced?	☐ Yes 🗵 No				
Was the carbon backflushed?	☐ Yes 区 No				

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	lssues/Notes/Comments	
Walchem Controller Inspected	⊠ Yes □ No		
Flow Meters Inspected	⊠ Yes □ No		
Level Sensor Cleaning/Inspection	⊠ Yes □ No		
Inspect System Plumbing	ĭ Yes ☐ No		
Pumps Inspected	ĭ Yes ☐ No		
General Housekeeping	☑ Yes ☐ No		
Chemistry Level	☑ Yes ☐ No	~70 gal	
Safety Materials Inspected	☑ Yes ☐ No		
pH Probe Inspection/Calibration	☑ Yes ☐ No	Verified with handheld, ok	



Water Sampling:									
Were water samples taken? ☐ Yes ☒ No									
Raw water:	pH <u>n/a</u>	Turbidity	n/a	_NTU					
Bag Filter Influent	pH 7.25	Turbidity _	4.13	NTU					
Bag Filter Effluent	pH7.15	Turbidity _	3.84	NTU					
Carbon Filter Influent	pHn/a	Turbidity _	n/a	_NTU					
Carbon Filter Effluent	pH <u>n/a</u>	Turbidity _	n/a	_NTU					
Monthly Tasks:									
Were samples submitt	ed to Analytical?	☐ Yes 区 No)						
Analytical Lab:		_							
Was Walchem data do	wnloaded?	☐ Yes ☒ No	o						
Were the tank sludge I	evels checked?	☐ Yes 区 No)						
Sludge Depth (inches):									
Decant Tank: n	/a								
Treatment tank:n	<u>/a</u>								
Backflush tank:n	/a								
Main lift station:n	<u>/a</u>								
North lift station:n	/a								
South lift station:n/	/a								
Additional Comments,	, Recommendatio	ons and Syste	m Upse	ets:					
Vault empty no flow System ran in recir	_		water	to disc	harge through carbon.				
David DuBoi	is	Project Le	ad Te	ch	6/19/19				
Technician		Titl	e	1124	Date				
		Subi	mit 🐇						

Page 2 of 2